

Elegance Round 2 Evolution Sensor


	EN	Assembly instructions
		-
	DE	Montageanleitung
	SK	Návod na inštaláciu
	PL	Instrukcja montażu
	CZ	Montážní návod
	HU	Szerelési útmutató
	BA	Upute za montažu
8	SI	Navodila za montažo
	HR	Upute za montažu
	RO	Instrucțiuni de montaj
	RS	Инструкције за уградњу
	BG	Инструкции за монтаж
	RU	инсталиране
	HL	Montage handleiding
	FR	Manuel d'installation
	IT	Instruzioni per l'nstallazione
	ES	Instrucciones de instalación
	SA	تعليمات التثبيت

- Before mounting and maintenance please make sure that the electrical supply has been switched off to avoid electric shock.
- Never look into the light directly when it is switched on.

Sicherheitshinweise

- Schalten Sie vor der Installation und vor Wartungsarbeiten stets die Spannungsversorgung ab.
- Schauen Sie bitte nicht direkt ins Licht, wenn die Leuchte eingeschaltet ist.

- EN Danger, installation by electricians only
- DE Lebensgefahr, Montage nur durch Elektrofachkraft
- SK Nebezpečenstvo úrazu elektrickým prúdom! Inštaláciu zariadenia môže vykonávať len kvalifikovaný elektrikár.
- PL Zagrożenie życia, montaż tylko przez wykwalifikowanego elektryka
- CZ Nebezpečí ohrožení života, instalaci může provádět pouze osoba znalá ve symslu vyhl. 50/78 Sb
- HU Életveszély, a szerelést csak szakképzett villanyszerelő végezheti
- BA Opasno po život, instalaciju može izvoditi samo stručna osoba
- SI Smrtno nevarno, vgradnja dovoljena samo pooblaščenim osebam.
- HR Opasno po život, instalaciju može izvoditi samo stručna osoba
- RO Pericol, montaj realizat doar de electricieni calificati
- RS Опасност, инсталирају само електричари
- BG Внимание, изисква се монтаж от електротехник
- RU Опасность для жизни, только при установке электрика
- HL Levensgevaar, installatie enkel door gekwalificeerde elektricien
- FR Danger de mort, installation uniquement par électricien qualifié
- IT Pericolo di morte, installazione solo tramite un'elettricista
- ES Peligro de muerte, sólo a través de electricista instalador
- خطرا على الحياة، إلا من خلال تركيب كهربائي 🛛 SA



-Only for color temperature selectable function

Model	Voltage	Current	PF	Wattage	Luminous Flux	W/Φ (mm)	H (mm)	ta(℃)
LILE0059	220-240V~	0.07A/0.05A	0.9	15////10///	10W - 1000LM (WW and NW) 15W - 1500LM (WW and NW)	220	53	40

Color Temperature: Warm White (WW): 3000K, Neutral White (NW): 4000K

RoHS CE



Schrack Technik GmbH Seybelgasse 13 AT-1230 Vienna www.schrack.com



IP54




Motion detecting with ON-OFF function

Settings


Step 1 - Detection Range								
Range Settings	1.0 - 1.25m		1.0 - 2.5m		1.0 - 3.5	im 1.	1.0 - 5.0m	
S1	ON			ON	OFF		OFF	
S2	ON			OFF	ON		OFF	
Step 2 - Lighting Timer Time	_	20		- ·		10 .	2411	
Settings	5 sec.	30 s	sec.	2 min.	5 min.	10 min	. 24 H	
S3	ON	0	Ν	ON	ON	OFF	OFF	
S4	ON C		Ν	OFF	OFF	ON	OFF	
S5	ON O		FF	ON	OFF	OFF	OFF	

Step 3 - Light Sensibility				
Sensibility Settings	OFF	10 lux	50 lux	100 lux
S6	ON	ON	OFF	OFF
S7	ON	OFF	ON	OFF




Detection Range: 1.0 - 3.5m Lighting timer: 2 min. Light sensitivity: 50 lux

Place of DIP Switch



Examples of Detection Range and Hights




Approximate values					
Height	Range				
1.0-2.5m	approx. 2.5m				
3.5m	approx. 5.0m				
4.5m	approx. 3.5m				




Bewegungserkennung mit Flurfunktion Einstellungen

Schritt 1 - Erfassungsbereich								
Bereich Einstellungen	1.0 - 1.25m		1.0	- 2.5m	1.0 - 3.5m		1.0 - 5.0m	
S1	ON		ON		OFF		OFF	
S2	ON			OFF	ON		OFF	
Schritt 2 - Beleuchtungstimer Zeit Einstellungen	5 sec.		sec.	2 min.	5 min.		min.	24 H
S3	ON	ON		ON	ON	0	FF	OFF
S4	ON	ON		OFF	OFF	ON		OFF
S5	ON	OFF		ON	OFF	0	FF	OFF


Schritt 3 - Helligkeitschaltwert						
Helligkeit Einstellungen	OFF	10 lux	50 lux	100 lux		
S6	ON	ON	OFF	OFF		
S7	ON	OFF	ON	OFF		



Position des DIP Schalters



Die Beispiele für den Erfassungsbereich und Höhen



Näherungswerte					
Höhe	Bereich				
1.0-2.5m	ca. 2.5m				
3.5m	ca. 5.0m				
4.5m	ca. 3.5m				