



For the installation of the fittings the 4 corners of the tank must be drilled to $\phi 7$, then the 4 metric screws are inserted from the inside and fastened with a nut from the outside

